



COMPONENT REPAIR CAPABILITIES

Contact us:

info@apacs.aero

+603 5870 0500

Feb-24

© 2023 Asia Pacific Aircraft Component Services Sdn Bhd. All rights reserved



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
04P23-10	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000	YES	YES	YES	YES	YES	YES	NO
04P23-12	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000	YES	YES	YES	YES	YES	YES	NO
04P23-8	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000	YES	YES	YES	YES	YES	YES	NO
07P95-1	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-2	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-3	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-4	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-7	VALVE PNEUMATIC RELAY	75-31-43;	GRIMES AEROSPACE CO	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-8	VALVE PNEUMATIC RELAY	75-31-43;	GRIMES AEROSPACE CO	YES	YES	YES	8747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
07P95-9	PNEUMATIC RELAY VALVE	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;A310;A330	YES	YES	YES	YES	YES	YES	NO
1001000-3	VALVE-STARTER-AIR	80-11-18;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
1001000-4	VALVE-STARTER-AIR	80-11-18;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
10-1327-1	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B737NG;B757;B767;	YES	YES	YES	YES	YES	YES	NO
10-1327-2	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
10-1327-3	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
10-1327-4	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B757;	YES	YES	YES	YES	YES	YES	NO
10-1733-1	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
10-1733-2	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737NG;B757;	YES	YES	YES	YES	YES	YES	NO
10-1733-3	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8737CL;B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
102-00090	SENSOR-OIL TEMPERATURE	79-32-15;	NORWICH AERO PRODUCTS INC.	YES	NO	NO	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
10-609660-9	IGNITION LEADS	74-21-08;	UNISON INDUSTRIES, LLC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
106-1-1100-02	ACTUATOR-APU	49-16-51;	ELEKTRO-METALL EXPORT GMBH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
106-1-1100-03	APU ACTUATOR	49-16-51;	ELEKTRO-METALL EXPORT GMBH	YES	YES	YES	A320; A330; A340	YES	YES	YES	YES	NO	NO	NO
10-62090-42	AUDIO CONTROL PANEL	23-50-38;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
10-62090-64	AUDIO CONTROL PANEL	23-50-23;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
10-62090-77	AUDIO CONTROL PANEL	23-50-74;	AVTECH TYEE, INC	YES	YES	YES	B737NG;A330;	YES	YES	YES	YES	YES	YES	NO
1108V0100-1	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1108V0100-2	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1108V0100-3	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
1109V0300	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A330;A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1109V0300-1	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A330;A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1109V0300-2	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A330;A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1109V0300-3	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
1109V0300-4	SOLENOID- HPC SECONDARY FLOW CONTROL	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	767;A300;A330;MD-11	YES	YES	YES	YES	NO	YES	NO
1110V0500-2	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0500-3	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0500-4	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0500-5	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0500-6	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8767;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0700-3	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0700-4	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
1110V0700-5	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0300-1	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0300-4	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0300-5	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0300-6	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-10	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-4	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-5	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-6	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-7	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-8	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
1115V0700-9	BLEED AIR VALVE 9TH.-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
114087004	VALVE-BYPASS,DOOR	32-31-25;	GE AVIATION SYSTEMS LIMITED	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087005	VALVE-BYPASS,DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087006	VALVE-BYPASS, DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087007	VALVE-BYPASS,DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087008	VALVE-BYPASS DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087009	VALVE-BYPASS DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
114087010	VALVE-BYPASS DOOR	32-31-25;	TRIUMPH ACTUATION SYSTEMS UK, LTD	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
11698-000	HEAT EXCHANGER AIR/OIL IDGS	24-11-01;	AMETEK AEROSPACE	YES	YES	YES	8747;B767;A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
11-841193-2	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
11-841193-3	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
11-841193-4	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	YES
1211313-010	ACTUATOR-VARIABLE STATOR	75-32-13;	ARKWIN INDUSTRIES INC.	YES	YES	YES	8737CL;B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-10	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-11	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-12	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-3	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-4	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-5	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-6	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
121664-7	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
121664-8	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121664-9	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
121666-13	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-14	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-16	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-17	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-18	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-19	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-21	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-3	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-4	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-6	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-7	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
121666-8	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL:A320_Fam:A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
1226400	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
123100-3	PDU-POWER DRIVE UNIT	25-58-29;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam:A330;A340;	YES	YES	YES	YES	YES	YES	NO
125A2	VISUAL INDICATOR	79-21-36;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	NO	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
125A3	VISUAL INDICATOR	79-21-36;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	NO	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
12698-000	HEAT EXCHANGER-AIR/OIL IDGS	24-11-01;	AMETEK AEROSPACE	YES	YES	NO	B767:A330;A300;A310;MD11;PW4000;	YES	YES	YES	YES	NO	YES	NO
1298A0000-01	VALVE-CHECK	21-62-15;	LIEBHERR AEROSPACE LINDENBERG GMBH	YES	YES	YES	A320_Fam:A330;	YES	YES	YES	YES	YES	YES	NO
1303A0000-03	VALVE-FLOW CONTROL	21-51-14;	LIEBHERR AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL:A320_Fam;	YES	YES	YES	YES	YES	YES	NO
1303A0000-04	VALVE-FLOW CONTROL	21-51-14;	LIEBHERR AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL:A320_Fam;	YES	YES	YES	YES	YES	YES	NO
1324M12P10	ACTUATOR-VARIABLE STATOR	75-32-13;	ARKWIN INDUSTRIES INC.	YES	YES	YES	B737CL;B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	NO	NO
14320-001-1	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-001-2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002-1	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002-2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002A1	TOILET ASSEMBLY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002A2	TOILET ASSEMBLY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002B1	TOILET ASSEMBLY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002B2	TOILET ASSY VAC	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002C1	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-002C2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-230-201	FLUSH VALVE ASSY	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-230-203	FLUSH VALVE ASSY	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-230-205	FLUSH VALVE ASSY	38-34-30;	Safran Aerosystems Services Europe	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14320-230-207	FLUSH VALVE ASSY	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004A1	TOILET ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004A2	TOILET ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004B1	TOILET ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004B2	TOILET ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004C1	TOILET ASSY	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	YES	B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-004C2	TOILET ASSY	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-008-1	TOILET ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-050	FLUSH VALVE ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	B737CL;B737NG;B757;B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14330-170	VALVE ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	NO	YES	YES	YES	YES	NO
14330-230	FLUSH VALVE ASSY	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B737NG;B757;B767;A320_Fam;EMB190;	YES	YES	YES	YES	YES	YES	YES
14330-260-1	TOILET BOWL	38-34-20		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
14330-260-2	TOILET BOWL	38-34-20		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
14400-230-1	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14400-230-2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14400-230A1	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14400-230A2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14400-230B2	TOILET ASSY	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
14401-029	FILTER	38-34-11;	MAG Aerospace Industries, Inc.	NO	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
1567A0000-01	VALVE-SELECTOR	52-30-16;	LIEBHERR AEROSPACE LINDENBERG GMBH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
15800-323	VALVE-ANTI-SYPHON TOILET	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	NO	YES	YES	YES	YES	NO
15800-348	VALVE - TOILET RINSE	38-34-16;	MAG Aerospace Industries, Inc.	YES	YES	YES	B737NG;B757;B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
15800-348A	VALVE ASSY-RINSE	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B737NG;B757;B767;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
15800-358	VALVE ASSY-RINSE	38-34-20;	MAG Aerospace Industries, Inc.	YES	YES	YES	B737NG;B757;B767;A320_Fam;	YES	YES	YES	YES	YES	YES	YES
15800-440	VALVE ASSY-RINSE	38-34-30;	MAG Aerospace Industries, Inc.	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
15801-165-1	TOILET BOWL	38-34-16;	MAG AEROSPACE INDUSTRIES, INC.	YES	YES	NO	A320_Fam;	YES	YES	YES	NO	YES	YES	NO
15801-165-2	TOILET BOWL	38-34-16;	MAG AEROSPACE INDUSTRIES, INC.	YES	YES	NO	A320_Fam;	YES	YES	YES	NO	YES	YES	NO
1605100	VISUAL INDICATOR	79-21-61;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
1605100-01	VISUAL INDICATOR	79-21-61;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
1605100-02	VISUAL INDICATOR	79-21-61;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
182820-2	HEAT EXCHANGER	21-50-14;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
182820-3	HEAT EXCHANGER	21-50-14;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
182820-4	HEAT EXCHANGER	21-50-14;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	NO	NO	NO	NO
1853M13P01	IGNITION LEADS	74-21-19;	UNISON INDUSTRIES, LLC	YES	YES	YES	B737CL;CFM56;	YES	YES	YES	YES	YES	YES	NO
1853M13P04	IGNITION LEADS	74-21-19;	UNISON INDUSTRIES, LLC	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	NO	YES	YES	NO
181384	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;	YES	YES	YES	NO	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
187405	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747,B767,A330,A300,A310,MD11;	YES	YES	YES	NO	YES	YES	NO
2041220-0401	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B747,DC10;	YES	YES	YES	YES	YES	YES	NO
2041220-0408	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	MD11;	YES	YES	YES	YES	YES	YES	NO
2041220-0409	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A330,A340;	YES	YES	YES	YES	YES	YES	NO
2041220-0410	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2041220-0413	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	MD11;	YES	YES	YES	YES	YES	YES	NO
2041220-0424	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2041220-3231	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2041223-0402	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
2041223-0410	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
2041223-0411	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
2041223-0424	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
2041223-3135	CONTROL UNIT-WEATHER RADAR	34-41-12;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	A320_Fam;	YES	YES	YES	NO	YES	YES	NO
2290B020000	CHECK VALVE-PRESS, INTERMED	36-11-04;	IEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;A340,V2500;	YES	YES	YES	YES	YES	YES	NO
2293B010000	CHECK VALVE-PRESS, INTERMED	36-11-04;	IEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;A340,CFM56;	YES	YES	YES	YES	YES	YES	NO
2293B020000	CHECK VALVE-PRESS, INTERMED	36-11-04;	IEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;A340,CFM56;	YES	YES	YES	YES	YES	YES	NO
2313M347-4	WINDSHIELD WIPER MOTOR LH	30-40-14;	Goodrich Electronic Systems (SIS)	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
2313M-347-4	WINDSHIELD WIPER MOTOR LH	30-40-14;	Goodrich Electronic Systems (SIS)	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
2313M348-4	WINDSHIELD WIPER MOTOR RH	30-40-14;	Goodrich Electronic Systems (SIS)	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
2313M-348-4	WINDSHIELD WIPER MOTOR RH	30-40-14;	Goodrich Electronic Systems (SIS)	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
236-508	AIR CHILLER 4500 BTU/HR	25-30-36;	B/E AEROSPACE INC.	YES	YES	YES	A330,A340,A310;	YES	YES	YES	YES	YES	YES	NO
236-8	REFRIGERATION UNIT-AIR CHILLER 4500 BTU	25-30-36;	B/E AEROSPACE INC.	YES	YES	YES	A330,A340,A310;	YES	YES	YES	YES	YES	YES	NO
238D1024-507	SWITCH-OP (PPK)	73-34-04;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A330,A340,CFM56-5C;	YES	YES	YES	YES	YES	YES	NO
2651-278-21	LAVATORY DRAIN BALL VALVE ASSY	38-38-09;	KAISER ELECTROPRECISION	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
2651-278-23	LAVATORY DRAIN BALL VALVE ASSY	38-38-09;	KAISER ELECTROPRECISION	YES	YES	YES	B757;	YES	YES	YES	YES	YES	YES	NO
2651-278-24	LAVATORY DRAIN BALL VALVE ASSY	38-38-09;	KAISER ELECTROPRECISION	YES	YES	YES	B757;	YES	YES	YES	YES	YES	YES	NO
267-100	AIR CHILLER	25-30-43;	B/E AEROSPACE INC.	YES	YES	YES	B737CL;B747;B757;B767;A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	YES
267-500	AIR CHILLER	25-30-43;	B/E AEROSPACE INC.	YES	YES	YES	B737CL;B747;B757;B767;A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2675V	AIR CHILLER	25-30-43;	B/E AEROSPACE INC.	YES	YES	YES	B737CL;B747;B757;B767;A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2740028-1	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	YES	NO	NO
2740028-2	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B737	YES	YES	YES	NO	YES	NO	NO
2740028-3	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B737	YES	YES	YES	NO	YES	NO	NO
2740028-4	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B737	YES	YES	YES	NO	YES	NO	NO
2740028-5	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B737	YES	YES	YES	NO	YES	NO	NO
2740028-6	ACTUATOR	21-51-94;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	YES	NO	NO
2-7680-2	FUSE ASSY FLOW RATE	27-32-02;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;B757;B767;	YES	YES	YES	YES	YES	YES	YES
2-7681-1	FLOW RATE FUSE ASSEMBLY	27-32-03;	Triumph Actuation System	YES	YES	YES	B737NG;B757;B767;B777;	YES	YES	YES	YES	YES	YES	NO
2-7681-2	FLOW RATE FUSE ASSEMBLY	27-32-03;	Triumph Actuation System	YES	YES	YES	B737NG;B757;B767;B777;	YES	YES	YES	YES	YES	YES	NO
2-8020-1	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8020-11	THRUST/R PRESS HYD FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
2-8020-12	STBY T/R HYD FUSE ASSY	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
2-8020-13	SLATS STAND BY HYD FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8020-15	LE FLAP SLAT HYD FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B757;	YES	YES	YES	YES	YES	YES	NO
2-8020-16	NLG HYD FUSE ASSY.	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
2-8020-18	HYD FUSE ASSY	32-31-04;	Triumph Actuation System	YES	YES	YES	B757;	YES	YES	YES	YES	YES	YES	NO
2-8020-2	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8020-24	T/R RTN HYD FUSE ASSY.	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
2-8020-25	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
2-8020-26	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
2-8020-27	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
2-8020-28	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
2-8020-29	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
2-8020-3	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8020-5	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8020-6	FUSE	32-31-04;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
2-8041-1	FUSE ASSY	32-40-18;	Triumph Actuation System	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
282-3	COMPRESSOR	25-31-03	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
282-6	COMPRESSOR	25-31-03	YES	YES	YES	NO	YES	NO	NO	NO	NO	NO	NO	NO
285T0855-1	FLT DECK ACCESS CONTROL MODUL	52-51-04;	BAE SYSTEMS CONTROLS INC.	YES	YES	YES	B737CL;B737NG;B747;B757;B767;	YES	YES	YES	YES	YES	YES	NO
285T0855-5	FLT DECK ACCESS CONTROL MODUL	52-51-04;	BAE SYSTEMS CONTROLS INC.	YES	YES	YES	B737NG;B747;A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2944T100-1	DRIVE UNIT-POWER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	B737CL;A320_Fam;A340;BAE146;	YES	YES	YES	YES	YES	YES	NO
2944T100-3	DRIVE UNIT-POWER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	B737CL;A320_Fam;A340;BAE146;	YES	YES	YES	YES	YES	YES	NO
2955530-1	ROLLER PDU	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2955810-1	ROLLER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2955810-3	ROLLER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2955T100-5	PDU-POWER DRIVE UNIT	25-51-19;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2955T100-7	PDU-POWER DRIVE UNIT	25-51-19;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2955T100-9	PDU-POWER DRIVE UNIT	25-51-19;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2LA003968-00	LIGHT-ANTICOLLISION,BEACON	33-42-04;	Goodrich Lighting Systems	YES	YES	NO	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
2LA004626-00	LIGHT FLIGHT CREW READING	33-11-11;	Goodrich Lighting Systems	YES	YES	NO	A330;A340;A310;FOKKER;	YES	YES	YES	YES	YES	YES	NO
2LA402515-00	ASSY STROBE LIGHT-ANTICOLLISION	33-42-04;	Goodrich Lighting Systems	YES	YES	NO	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO
2LA403702-01	LT NAV	33-41-15;	Goodrich Lighting Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
2LA403702-02	LIGHT-NAVIGATION REAR	33-41-15;	Goodrich Lighting Systems	YES	YES	NO	A320_Fam;A330,A340;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
2LA455010-00	LIGHT-ANTICOLLISION,BEACON	33-42-24;	Goodrich Lighting Systems	YES	YES	NO	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
30-0909-1	LIGHT - TAILCONE ANTI COLLISION	33-40-38;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
30-0909-101	LIGHT - TAILCONE ANTI COLLISION	33-40-38;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
30-0909-201	LIGHT - TAILCONE ANTI COLLISION	33-40-38;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
301-776-206-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-776-207-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-776-305-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-776-306-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-780-702-0	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-780-703-0	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-780-704-0	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-781-402-0	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-781-403-0	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-781-404-0	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-781-405-0	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-789-101-0	HEATER-SERVO FUEL	73-11-24;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B737NG;A320_Fam;A340;CFM56-78, CFM56-5C, CFM56-5B	YES	YES	YES	YES	YES	YES	NO
301-789-102-0	HEATER-SERVO FUEL	73-11-77;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-790-101-0	COOLER-IDG OIL	73-11-64;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-791-301-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-791-302-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-792-702-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-792-703-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-792-801-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-792-802-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-792-803-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-793-901-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-793-902-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-793-951-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-793-952-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-797-503-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-797-601-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-797-602-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-797-603-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-799-403-0	VISUAL INDICATOR	79-21-61;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-800-401-0	CHIP DETECTOR	79-21-57;	CFMI C/O SAFRAN	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
301-801-201-0	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-801-301-0	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
301-807-203-0	FILTER-FUEL DOWN STREAM	73-11-47;	Safran Filtration systems	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3022053-000	PUMP-HYDRAULIC	29-10-56;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
3022053-001	PUMP-HYDRAULIC	29-10-56;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
3022151-000	PUMP-HYDRAULIC	29-10-56;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
30-2505-3	ANTICOLLISION LIGHT UPPER FUSELAGE	33-42-03;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
30-2506-3	ANTICOLLISION LIGHT, LOWER FUSELAGE	33-42-04;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
3031863-001	PUMP-HYDRAULIC	29-11-34;	EATON AEROSPACE	YES	YES	YES	B747;B757;B767;A320_Fam;A300;CFM56;JT8;	YES	YES	YES	YES	YES	YES	NO
3217-100	VALVE-RAIN REPELLENT	30-45-11;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737CL;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
3217-200	VALVE-RAIN REPELLENT	30-45-11;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737CL;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
3231708-2	SCREW AND NUT ASSY-BALL	75-31-51		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
3231708-3	SCREW AND NUT ASSY	75-31-51		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
3238052-2	FLAPPER	75-31-51		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
3238052-4	FLAPPER	75-31-51		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
327155-1	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
327155-2	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
327155-3	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
3282970-2	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
3282970-3	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3282970-4	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3282970-5	STOP MECHANISM-BLEED VALVE	75-31-22;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	NO	YES	NO
3289562-5	VALVE-PRECOOLER	36-13-91;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;CFM56;	YES	YES	YES	YES	NO	NO	NO
3289562-6	VALVE-PRECOOLER	36-13-91;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;CFM56;	YES	YES	YES	YES	NO	NO	NO
3289562-7	VALVE-PRECOOLER	36-13-91;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;CFM56;	YES	YES	YES	NO	NO	NO	NO
3290064-10	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B757;BDV;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3290064-13	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A340;	YES	YES	YES	YES	YES	YES	NO
3290064-17	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B757;BDV;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3290064-18	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	CFM56;	YES	YES	YES	YES	YES	YES	NO
3290064-19	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3290064-20	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B757;BDV;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
3290064-30	VALVE-STARTER	80-11-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
337-075-103-0	LUBRICATION UNIT	21-15CFMI-TP.CM.;	SNECMA MOTEURS (GROUPE SNECMA)	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
337-075-104-0	LUBRICATION UNIT	21-15CFMI-TP.CM.;	SNECMA MOTEURS (GROUPE SNECMA)	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
337-075-105-0	LUBRICATION UNIT	21-15CFMI-TP.CM.;	SNECMA MOTEURS (GROUPE SNECMA)	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
340-400-004-0	UNIT-LUB	79-21-16;	CFMI C/O SAFRAN	YES	YES	YES	B737NG;A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
340-400-005-0	UNIT-LUB	79-21-16;	CFMI C/O SAFRAN	YES	YES	YES	B737NG;A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
340-402-602-0	ACTUATOR-VBV	75-32-14;	GE AVIATION SYSTEMS LIMITED	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
340-402-603-0	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO
340-402-604-0	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO
340-402-653-0	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO
340-403-003-0	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
340-403-004-0	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
340-403-101-0	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	CFM56;	YES	YES	YES	NO	YES	YES	NO
340-403-102-0	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
3428040000	THERMOSTAT-CONTROL	36-11-47;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
3428050000	THERMOSTAT-CONTROL	36-11-47;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
350880-6	ENGINE DRIVEN PUMP	29-11-03;	EATON AEROSPACE	YES	YES	YES	B747;B757;B767;A320_Fam;A300;CFM56;JT8;	YES	YES	YES	YES	YES	YES	NO
350880-7	ENGINE DRIVEN PUMP	29-11-04;	EATON LIMITED	YES	YES	YES	B747;B757;B767;A320_Fam;A300;CFM56;JT8;	YES	YES	YES	YES	YES	YES	NO
3830032-105	VALVE OIL COOLER BYPASS	79-21-16;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
3878040000	THERMOSTAT	36-11-20;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A340;	YES	YES	YES	YES	YES	YES	NO
3878050000	THERMOSTAT	36-11-20;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A340;	YES	YES	YES	YES	YES	YES	NO
3880010000	THERMOSTAT	36-11-78;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
38E93-5	VALVE-CONTROL,WING ANTI ICING	30-11-52;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
38E93-6	VALVE-CONTROL,WING ANTI ICING	30-11-52;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
3978030000	THERMOSTAT-SOLENOID	36-11-36;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
398-21	FILTER	36-11-35;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
398908-2	TEMPERATURE CONTROL VALVE	21-50-83;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	NO	NO	NO
398908-3	TEMPERATURE CONTROL VALVE	21-50-83;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	YES	NO	NO	YES
398908-4	TEMPERATURE CONTROL VALVE	21-50-83;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	NO	NO	NO
398908-5	TEMPERATURE CONTROL VALVE	21-50-83;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	NO	NO	NO
398908-6	TEMPERATURE CONTROL VALVE	21-50-83;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737	YES	YES	YES	NO	NO	NO	NO
3988050000	THERMOSTAT	36-11-35;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
3988060000	THERMOSTAT	36-11-35;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;	YES	YES	YES	YES	NO	YES	NO
398E020000	THERMOSTAT	36-11-35;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
398E030000	THERMOSTAT	36-11-35;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
4041-48	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	YES
4041-58	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	YES
4041-70	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	YES
4042-10	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
41F1004	UNIT-LUB	79-21-16;	CFMI C/O SAFRAN	YES	YES	YES	B737NG;A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
41F1005	UNIT-LUB	79-21-16;	CFMI C/O SAFRAN	YES	YES	YES	B737NG;A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
4205400	PUMP-HYDRAULIC	29-11-33;	PARKER HANNIFIN MANUFACTURING	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
4205401	PUMP-HYDRAULIC	29-11-33;	PARKER HANNIFIN MANUFACTURING	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
42D362	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
42D394	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
42D395	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	YES
4313100-01-6600	CONVECTION OVEN DF3000 LH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
4313101-01-6600	CONVECTION OVEN DF3000 RH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
4323070-01-6626	STEAM OVEN DS3075 LH (EXTENDED VERSION)	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B777	YES	YES	YES	YES	YES	YES	NO
4323100-01-6622	STEAM OVEN DS3000 LH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
4323101-01-6622	STEAM OVEN DS3000 RH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B777	YES	YES	YES	YES	YES	YES	NO
45-0351-1	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-2	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45-0351-3	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-4	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45-0351-5	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-6	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45332-8036	OIL / FUEL HEAT EXCHANGER	79-21-26;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
45332-8039	OIL / FUEL HEAT EXCHANGER	79-21-26;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	YES
45731-1381	HEATER-SERVO FUEL	73-11-24;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B737NG;A320_Fam;A340;CFM56-7B, CFM56-5C, CFM56-5B	YES	YES	YES	YES	YES	YES	NO
45731-1382	HEATER-SERVO FUEL	73-11-77;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	YES
45731-1385	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
45731-1386	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
45731-1391	COOLER-IDG OIL	73-11-64;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
45731-1392	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	CFM56;	YES	YES	YES	YES	YES	YES	NO
45731-1393	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	YES
45D31	SWITCH-DIFFERENTIAL PRESSURE	73-34-03;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A320_Fam;CFM56-5A;CFM56-5B;	YES	YES	YES	YES	YES	YES	NO
45D31-2	SWITCH-OP (PPK)	73-34-04;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A330;A340;CFM56-5C;	YES	YES	YES	YES	YES	YES	NO
45D32	SWITCH-LOW OIL PRESSURE	79-33-02;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
47111-1201	EXCHANGER, HEAT -IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
47111-1203	EXCHANGER, HEAT -IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
47111-1204	EXCHANGER, HEAT -IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
50U683	IGNITION LEADS	74-21-08;	UNISON INDUSTRIES, LLC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
5145-1-42	AUDIO CONTROL PANEL	23-50-38;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B0IV;	YES	YES	YES	YES	YES	YES	NO
5145-1-60	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
5145-1-61	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
5145-1-62	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
5145-1-64	AUDIO CONTROL PANEL	23-51-23;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
5145-1-77	AUDIO CONTROL PANEL	23-50-74;	AVTECH TYEE, INC	YES	YES	YES	B737NG;A330;	YES	YES	YES	YES	YES	YES	NO
5145-1-83	SEALED AUDIO CONTROL PANEL	23-44-00;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B0IV;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
5145-1-88	SEALED AUDIO CONTROL PANEL	23-44-02;	AVTECHTVEE	YES	YES	YES	B737 Family	YES	YES	YES	YES	YES	YES	NO
51H336	VALVE OIL COOLER BYPASS	79-21-16;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
51R148	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	NO	YES	YES	NO
51U711	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
541674-4	ACTUATOR - RAM AIR INLET	21-20-36;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	NO	NO
5507-910-0	CHIP DETECTOR	79-21-57;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-002	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	NO	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-005	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-006	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-007	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-02R	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-05R	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
582-3	COMPRESSOR	25-31-12		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
5830201-106	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-107	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B747;B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-108	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-109	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-110	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-111	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-105	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-106	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-108	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-109	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-111	VALVE-TURBINE CASE CLG	75-24-15;	PARKER HANNIFIN MANUFACTURING	YES	YES	YES	767	YES	YES	YES	YES	YES	YES	NO
5830203-104	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-09;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830203-105	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-09;	PARKER HANNIFIN CORPORATION	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
585-14	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-16	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-17	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-23	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	NO	YES	YES	NO
585-30	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	NO	YES	YES	NO
585-6	COMPRESSOR	25-31-15		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
585-8	COMPRESSOR	25-31-15		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
585-9	COMPRESSOR	25-31-15		YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
5930638-102	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-30;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930638-103	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-30;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-102	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-103	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-104	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
62197-001-001	WATER BOILER	25-35-95;	Safran Cabin Germany	YES	YES	YES	B737CL;B737NG;B767;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	YES
623977	PUMP-HYDRAULIC	29-11-34;	EATON AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
642D0010-503	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
642D0010-505	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
642D0010-507	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
66087	ENG DRIVEN HYD PUMP(A SYS)	29-11-34;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B747;B757;B767;A320_Fam;A300;CFM56;JT8;	YES	YES	YES	YES	YES	YES	NO
693335	PUMP - ELECTRIC	1-20;29-21-21; 29-2	EATON AEROSPACE	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
7074-100	ACTUATOR-VBV	75-32-14;	GE AVIATION SYSTEMS LIMITED	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO
7074-200	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	NO
7074-300	ACTUATOR-VBV	75-32-14;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	NO	YES
72180131	WATER BOILER DR6-2B	25-33-65;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
721840028	WATER HEATER DR40	25-33-40;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72184003	WATER HEATER	25-33-40;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
721840038	WATER HEATER	25-33-40;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;B757;B767;A320_Fam;A330;A340;A300;	YES	YES	YES	YES	YES	YES	NO
72184006	RAPID WATER BOILER	25-33-40;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
721840128	WATER HEATER	25-33-40;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;B747;A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
72184100	WATER HEATER DR4100	25-33-48;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72184101	WATER HEATER	25-33-48;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72184105	WATER HEATER	25-33-48;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72184110	WATER HEATER	25-33-48;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72184113	HEATER	25-33-48;	ROYAL INVENTUM COMPANY BV	YES	YES	YES	B737CL;B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
72603-1	FILTER-PILOT VALVE	30-11-52;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
753A0000-03	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
753A0000-04	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
753B0000-02	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
753B0000-03	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
753C0000-01	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
753C0000-02	EXCHANGER-HEAT,PRIMARY	21-52-11;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	B737CL;A320_Fam;	YES	YES	YES	YES	YES	YES	NO
754A0000-03	EXCHANGER-HEAT,MAIN	21-52-12;	LIEBHERR-AEROSPACE LINDENBERG GMBH	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
754B0000-02	EXCHANGER-HEAT,MAIN	21-52-12;	LIEBHERR-AEROSPACE LINDENBERG GMBH	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
754C0000-01	EXCHANGER-HEAT,MAIN	21-52-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
755A0000-04	REHEATER - AIR CONDITIONING	21-52-08;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
755B0000-02	REHEATER - AIR CONDITIONING	21-52-08;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
755C0000-01	REHEATER - AIR CONDITIONING	21-52-08;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
756A0000-05	CONDENSER	21-52-10;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
756A0000-06	CONDENSER	21-52-10;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
7589149	FILTER HPC BLEED AIR	75-24-19;	United Technologies Corp.	YES	YES	YES	B767/PW4000;	YES	YES	YES	NO	YES	YES	NO
7589149-101	FILTER HPC BLEED AIR	75-24-19;	PTI TECHNOLOGIES INC.	YES	YES	YES	B767/PW4000;	YES	YES	YES	NO	YES	YES	NO
7589149-102	FILTER HPC BLEED AIR	75-24-19;	PTI TECHNOLOGIES INC.	YES	YES	YES	PW4000;	YES	YES	YES	NO	YES	YES	YES
761A0000-03	ACTUATOR-INLET	21-53-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	NO	NO
761A0000-04	ACTUATOR-INLET	21-53-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	NO	NO
76180000-01	ACTUATOR-INLET	21-53-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	NO	NO
762A0000-03	AIR OUTLET ACTUATOR	21-53-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	NO	NO	NO
762A0000-04	ACTUATOR-OUTLET	21-53-12;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	NO	NO
763A0000-02	SENSOR-TEMPERATURE	21-52-18;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	NO	NO	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
763A0000-03	SENSOR-TEMPERATURE	21-52-18;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	NO	NO	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
764A0000-03	SENSOR-DUCT TEMP	21-52-22;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	NO	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
76480000-01	SENSOR-TEMPERATURE	21-52-22;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	NO	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
76480000-02	SENSOR-TEMPERATURE	21-52-22;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	NO	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
766A0000-01	SENSOR-TEMPERATURE	21-52-28;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
76680000-01	SENSOR-PNEUMATIC OVERHEAT	21-52-28;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
775538-15	STARTER CONTROL VALVE	80-12-05;	HAMILTON SUNDSTRAND	YES	YES	YES	A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
808810-1	VALVE-BYPASS ASSY	79-21-17;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
808810-2	VALVE-BYPASS ASSY	79-21-17;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
808900-1	VALVE-HEAT EXCHANGER ENG AIR/OIL	79-21-24;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	NO	YES	NO
81000-37601	LOGO LIGHT LH	33-45-04;	KOITO MFG CO. LTD	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
81000-37602	LOGO LIGHT RH	33-45-04;	KOITO MFG CO. LTD	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
811149-1	ACTUATOR-TURB CLG VALVE	75-24-28;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
8378M12	COMPRESSOR-AIR	38-42-51;	CEF INDUSTRIES, INC.	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
8378M2	COMPRESSOR-AIR	38-42-51;	CEF INDUSTRIES, INC.	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
84958	ENG DRIVEN HYD PUMP(A SYS)	29-10-61;	EATON AEROSPACE	YES	YES	YES	B737;CFM56-7B	YES	YES	YES	YES	YES	YES	YES
86500-109	VALVE WATER SHUTOFF	38-32-59;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
86500-109AMDTB	VALVE-WATER SHUTOFF	38-32-59;	Diehl Aviation Gilching GmbH	YES	YES	NO	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
86500-109AMDTG	VALVE-WATER SHUTOFF	38-32-59;	Diehl Aviation Gilching GmbH	YES	YES	NO	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
86600-103	VALVE, FLUSH ROTARY	38-32-78;	Diehl Aviation Gilching GmbH	YES	YES	NO	A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
86600-103REVL	VALVE, FLUSH ROTARY	38-32-78;	Diehl Aviation Gilching GmbH	YES	YES	NO	A340;	YES	YES	YES	YES	YES	YES	NO
887673	PUMP-HYDRAULIC	29-11-34;	EATON AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89010-001	BOWL	38-32-41		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
89010-101	BOWL	38-32-41		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
89-01-07000	HANDSET-COCKPIT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07010	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
89-01-07020	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07032	HANDSET-CABIN, FLIGHT ATTENDANT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07035	HANDSET-CABIN, FLIGHT ATTENDANT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07042	HANDSET-CABIN, FLIGHT ATTENDANT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07045	HANDSET-CABIN, FLIGHT ATTENDANT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07062	HANDSET-CABIN	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07122	HANDSET-CABIN	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07125	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07130	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07152	HANDSET-CABIN	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07154	HANDSET-CABIN	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07155	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07185	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
89-01-07250	HANDSET, COCKPIT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07260	HANDSET, COCKPIT	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
89-01-07350	HANDSET	23-73-01;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A330;	YES	YES	YES	YES	YES	YES	NO
9043110-16	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9043110-17	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
9043110-18	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9043110-3	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9043110-5	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
9059110-1	IGNITION LEADS	74-21-19;	UNISON INDUSTRIES, LLC	YES	YES	YES	B737CL;CFM56;	YES	YES	YES	YES	YES	YES	YES
9059110-2	IGNITION LEADS	74-21-19;	UNISON INDUSTRIES, LLC	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P09	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P14	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A340;CFM56;	YES	YES	YES	NO	YES	YES	NO
9387M24P16	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P17	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P18	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
971844	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
972630	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974540	HYDRAULIC MOTORPUMP ASSEMBLY	29-10-72;	EATON LIMITED	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
974800	PUMP-HYDRAULIC	29-10-55;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974947	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974976	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
975A0000-02	ACTUATOR-RAM AIR INLET	21-53-51;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
975A0000-03	ACTUATOR-RAM AIR INLET	21-53-51;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
976A0000-02	ACTUATOR-RAM AIR OUTLET	21-53-52;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	NO	NO
9910-000000-01	BOWL	38-32-42		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
A05000	ACTUATOR ASSY	24-09-01;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	NO	NO
A05800	ACTUATOR ASSY	24-09-01;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	NO	NO
A06000	ACTUATOR ASSY	24-09-02;	SITEC AEROSPACE GMBH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO
A08000	ACTUATOR ASSY	24-09-03;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
ACP2788AA02	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES		YES	YES	YES	NO	YES	YES	NO
ACP2788AB04	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
ACP2788AB05	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
ACP2788AC01	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES		YES	YES	YES	NO	YES	YES	NO
ACP2788AD01	ACP-AUDIO CONTROL PANEL	23-51-54;	COBHAM Avionics	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
ACP2788AE01	ACP-AUDIO CONTROL PANEL	23-51-55;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
ACP2788AF01	ACP-AUDIO CONTROL PANEL	23-51-01;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
C143620-2	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C143620-2M2	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C143620-3	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C148275-1	VALVE NACELLE COOLING	75-26-11;	MICROTECNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C20105000	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105000-1	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105000-2	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105100	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20105100-1	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20288000-1	ACCUMULATOR-BRAKE	32-46-06;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20288000-2	ACCUMULATOR-BRAKE	32-46-06;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C24960000-1	VALVE-SAFETY	29-11-67;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C24960000	VALVE SAFETY	29-11-67;	Safran Landing Systems	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
C82L0010	VALVE-DRAIN	29-11-13;	GOODRICH ACTUATION SYSTEMS SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D05000	VALVE-FILL AND DRAIN	38-10-02;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	NO	NO
D05A00	VALVE-FILL/ DRAIN	38-10-02;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
D05C00	VALVE-FILL AND DRAIN	38-10-02;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
D23119500	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119500-1	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119510	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
D23119510-1	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
D23119550	BOX-ELECTRICAL,NLG	32-57-11;	Safran Landing Systems	YES	YES	NO	A330;A340;	YES	YES	YES	YES	YES	YES	NO
D23119750	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119750-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119751	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119751-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119760	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119760-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119761	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119770-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119771	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
E61751-00-0001	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
E61751-00-0002	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
E61751-00-0003	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
FA00631B	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
FA00631C	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
FA00914D	FILTER-FUEL DOWN STREAM	73-11-47;	Safran Filtration systems	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
FCM9130-01	MODULE - FLUSH CONTROL	38-31-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
FCU9811-01	CONTROL UNIT-FLUSH	38-32-73;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	NO	YES	YES	NO
FCU9816	CONTROL UNIT-FLUSH	38-32-73;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO
FRH340003H	DRAIN VALVE-WASTE WATER	38-30-30;	Eaton Aerospace LTD	YES	YES	YES	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
FV9930-00	VALVE ASSY-FLUSH	38-32-79;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
FV9930-01	VALVE ASSY-FLUSH	38-32-41;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
G540DA51-01	VALVE-WASTE DRAIN	38-32-49;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
G540DA72	SEPARATOR-WASTE	38-34-19;	Diehl Aviation Gilching GmbH	YES	YES	NO	B767;A330;A340;	YES	YES	YES	YES	YES	YES	NO
G7402-05	PANEL-SINGLE ADF CONTROL	34-50-48;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
G7403-03	ADF PANEL	34-50-53;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;BDIV;	YES	YES	YES	YES	YES	YES	YES
G7404-124	RADIO TUNING PANEL	23-10-37;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;BDIV;EMB190;	YES	YES	YES	YES	YES	YES	YES
G7500-03	PANEL-VHF NAV CONT	34-50-57;	GABLES ENGINEERING INC.	YES	YES	YES	B737CL;B737NG;BDIV;	YES	YES	YES	YES	YES	YES	YES
GTA43-2	VALVE-HEAT EXCHANGER ENG AIR/OIL	79-21-24;	HAMILTON SUNDSTRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	NO	NO	YES	NO
J540A11-300	TOILET ASSY	38-32-41;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J540A11-500	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J540A11-510	TOILET ASSY	38-32-44;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
J540A11-520	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J540A12-300	TOILET ASSY	38-32-41;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J540A12-500	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J540A12-510	TOILET ASSY	38-32-44;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
J540A12-515	TOILET ASSY	38-32-44;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
J540A12-520	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-604	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
L83A13-609	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
L83A13-610	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A13-611	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-614	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-615	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
L83A13-616	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A602	VALVE WATER DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A603	VALVE WATER DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A310;	YES	YES	YES	YES	YES	YES	NO
N40-1A10100-101	HANDSET, COCKPIT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1A10102-101	HANDSET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GmbH & Co. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	NO	YES	NO
N40-1A40204-102	HANDSET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	NO	YES	NO
N40-1A40212-102	INTERPHONE HANDSET	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B10100-000	HANDSET, FLIGHT DECK, PAX, BLACK	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B10100-101	HANDSET-COCKPIT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20203-102	HANDSET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A330;	YES	YES	YES	YES	YES	YES	NO
N40-1B20212-102	HANDSET-CABIN	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20215-000	HANDSET, CABIN, PAX, FOGGY (VD9240)	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20215-102	HANDSET WITH SUPPORT BRACKET CABIN, PAX	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20218-102	HANDSET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1B30203-102	HANDSET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B30212-000	HANDSET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1B40203-102	HANDSET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40204-102	HANDSET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40212-102	HANDSET-CABIN	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40215-102	HANDSET-CABIN	44-10-03;	HOLMBERG GMBH & CO. KG	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
PV3-240-18	ENG DRIVEN HYD PUMP(A SYS)	29-10-61;	EATON AEROSPACE	YES	YES	YES	B737;CFM56-7B	YES	YES	YES	NO	YES	YES	NO
PV3-300-13E	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13F	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13H	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13K	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13L	PUMP-HYDRAULIC	29-10-55;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	NO	YES	YES	NO
R295530-1	ROLLER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	NO	NO
S283A305-1	ANTICOLLISION LIGHT UPPER FUSELAGE	33-42-03;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
S283A305-2	ANTICOLLISION LIGHT, LOWER FUSELAGE	33-42-04;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
S283A321-1	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	NO	YES	YES	NO
S283A321-2	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S283A321-3	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	NO	YES	YES	NO
S283A321-4	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S283A321-5	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	NO	YES	YES	NO
S283A321-6	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S417N514-301	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S417N514-48	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S417N514-58	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S417N514-70	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	NO	YES	NO
SB2091A1-1483	ACCUMULATOR-HYDRAULIC	29-11-12;	HYDAC SYSTEMS & SERVICES	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
SB2091A1-1484	ACCUMULATOR-HYDRAULIC	29-11-12;	HYDAC SYSTEMS & SERVICES	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TA9115-00	TOILET ASSY LH	38-31-61;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA9116-00	TOILET ASSY	38-31-61;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
TA9125-00	TOILET ASSY RH	38-31-61;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA9126-00	TOILET ASSY	38-31-61;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
TA911-03CE00-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03CE01-01	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03CE01-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03CE11-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE00-01	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE00-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE01-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE02-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE03-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE11-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-03PE13-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA911-993000-05	ARMREST, CAPTAIN ASSY	25-11-31;	STELIA AEROSPACE	NO	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-13CE10-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TA912-13CE11-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TA912-13PE10-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE00-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE01-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE10-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE11-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE20-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE21-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE30-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TA912-33CE31-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO



Asia Pacific Aircraft Component Services Sdn Bhd
Component Repair Capabilities
Version: February 2024

Contact us:
info@apacs.aero
+603 5870 0500

MPN	Description	CMMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
TAAI2-33PE00-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE01-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE10-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE11-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE20-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE21-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE30-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE31-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE00-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE01-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE02-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE10-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE11-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE12-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE20-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE21-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE22-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE30-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE31-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE32-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE00-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE01-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE02-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE10-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE11-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE12-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE20-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE21-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE22-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE31-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE32-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04IM20-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04IM30-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04IM40-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04IM50-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-14IM20-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
VA4110	FAN-RECIRCULATION	21-21-18;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
VD3810	MIXED FLOW FAN	21-21-12;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
VD3820	MIXED FLOW FAN	21-21-11;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
VD3820-01	MIXED FLOW FAN	21-21-11;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
VD3900-03	FAN-RECIRCULATION CABIN	21-21-16;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
VD3901-00	FAN-RECIRCULATION CABIN	21-21-16;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
VD3909-00	FAN-RECIRCULATION CABIN	21-21-19;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
VD3920	FAN-EXTRACTION AFT CARGO	21-21-14;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-02	FAN RECIRCULATION	21-21-17;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-03	FAN-RECIRCULATION	21-21-17;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-04	FAN-RECIRCULATION	21-21-17;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
WV9135-01	VALVE-WATER SHUTOFF	38-31-53;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
YG101-04	GUIDE-Y	25-51-02;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO