



Transport Canada Civil Aviation
Standards Branch (AARTM)
330 Sparks Street
Ottawa, ON K1A 0N5
Canada

Company File
5015 – 19874

2024-04-22

Mahesan Panjalingam
Asia Pacific Aircraft Component Services Sdn Bhd
Lot 3, Jalan Keluli 15/16,
Seksyen 15, 40200 Shah Alam,
Selangor, Malaysia

Authorization of FAA-certificated Repair Station located outside the United States

Dear Mahesan Panjalingam,

This letter authorizes Asia Pacific Aircraft Component Services Sdn Bhd, Certification No. 33SY148B to perform maintenance and modifications on aeronautical products, excluding aircraft, under TCCA regulatory control pursuant to Section B, paragraph 4.0, of the FAA/TCCA Maintenance Implementation Procedures (MIP).

This authorization is limited to specific components manufactured by Honeywell International Inc., Liebherr-Singapore Pte. Ltd., Diehl Aviation Gilching GmbH, CFM International, Inc. Gables Engineering and Meggitt Aerospace Ltd. The work performed must be within the ratings and limitations contained in your 14 CFR Part 145 certificate, operations specifications and current capability list revision 23 dated 2024-02-01. Any changes applied to your certificate, operations specifications, or capability list will invalidate this authorization and a new authorization request will be required by TCCA.

This TCCA authorization shall remain in effect until your FAA Repair Station Certificate expires 2024-10-31, or if the certificate has been surrendered, suspended or revoked. To renew this authorization, TCCA requires Asia Pacific Aircraft Component Services Sdn Bhd to provide their renewed certificate, and demonstrate compliance with the MIP, Section B, paragraph 4.1 as part of their new authorization request.

Best regards,



Craig Dennis
Civil Aviation Safety Inspector, Operational Airworthiness
Approved Organization Standards / Standards Branch